

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/01/2020

Submitted Date:

05/14/2020

Document Number:

690900097

FIELD INSPECTION FORM
 Loc ID 414031 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10619

Name of Operator: INSPIRE OIL & GAS INC

Address: 1400 BROADFIELD BLVD SUITE 600

City: HOUSTON State: TX Zip: 77084

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

10 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Waldron, Emily		emily.waldron@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Ritz, Bo	713-269-4969	britz@inspireoilandgas.com	
Colby, Lou		lou.colby@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412127	WELL	PR	10/20/2012	GW	057-06490	Silver Spur Minerals 35-2H	EI

General Comment:

On May 1, 2020 COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of Inspire Oil and Gas Inc.'s Silver Spur Minerals 35-2H, API 05-057-06490. Weather was sunny and temperature 63 degree F. For the most recent field inspection report of this facility, please refer to document #694500143. Note: The corrective action (CA) dates of document #689800259 and previous inspections remain.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Sign not posted or information inaccurate at entrance off of Hwy 14.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/03/2019
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery. Note: Produced water tanks signage, labeling, and placarding illegible.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	10/03/2019
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/03/2019

Emergency Contact Number:

Comment:	Location sign off of Hwy 14. (Note: phone number was not active on 9/3/2019). Well sign. (Note: phone number was not active on 9/3/2019). Produced water tanks signage, labeling, and placarding illegible.		
Corrective Action:	Install sign to comply with Rule 210.d. Install sign to comply with Rule 210.e.	Date:	10/04/2019

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Tubing and misc equipment stored on Location.		
Corrective Action:	Comply with Rule 603.f.	Date:	10/13/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
Condensate	Tank	<= 1 bbl		
Comment:	Tank 0030, staining beneath hammer unions.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.			Date: 09/04/2019

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:	Produced water tanks signage, labeling, and placarding illegible.				
Corrective Action:	Install sign to comply with Rule 210.d.			Date:	10/04/2019

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Earth	Adequate	Walls Insufficient			Inadequate	
Comment: Berm is not consolidated.						
Corrective Action: Repair or install berms or other scndary containment devices per Ruls 605.a.(4).						Date: 10/13/2017
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST			
Comment: Signage, labeling, and placarding illegible.						
Corrective Action: Install sign to comply with Rule 210.d.						Date: 10/04/2019
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Earth	Adequate	Walls Insufficient			Inadequate	
Comment: Berm is not consolidated.						
Corrective Action: Berm is not consolidated.						Date: 10/13/2017
Venting:						
Yes/No						
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities

Facility ID: 412127 Type: WELL API Number: 057-06490 Status: PR Insp. Status: EI

COGCC Comments

Comment	User	Date
<p>Note: The corrective action (CA) dates of document #689800259 and previous inspections remain. The operator shall immediately address the drips from the leaking hammer unions.</p> <p>The well appears to be SI at time of inspection</p>	fischera	05/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402398406	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5150526
690900098	INSP Photo Silver Spur Min 0505706490 20200501ajf	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5150517