

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402404717

Date Received:

05/22/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 5201 TRUXTUN AVENUE #100

City: BAKERSFIELD State: CA Zip: 90339

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Jon Armstrong

661-616-3941

jarmstrong@bry.com

John Hyder

435-823-1861

jhyder@bry.com

Don Wilbourn

970-285-5207

dwilbourn@bry.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689704637

Inspection Date: 05/01/2020

FIR Submit Date: 05/04/2020

FIR Status: _____

Inspected Operator Information:

Company Name: BERRY PETROLEUM COMPANY LLC

Company Number: 10091

Address: 5201 TRUXTUN AVENUE #100

City: BAKERSFIELD State: CA Zip: 90339

LOCATION - Location ID: 335820

Location Name: CHEVRON H07A 696 Number: _____ County: _____

Qtrqr: SENE Sec: 7 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.540239 Longitude: -108.140458

FACILITY - API Number: 05-045- -00 Facility ID: 335820

Facility Name: CHEVRON H07A 696 Number: _____

Qtrqr: SENE Sec: 7 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.540239 Longitude: -108.140458

CORRECTIVE ACTIONS:

1 ☒ CA# 138588

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/23/2020

Response: CA COMPLETED

Date of Completion: 05/15/2020

Operator Comment: Corrective action work on the culvert and basin was completed by 5/15/2020. The culvert was cleared of debris and raised to hopefully reduce the clogging issues seen at the lower gradeline. Rock guarding was installed at the new pipe elevation to prevent erosion around the pipe. Additionally, the inlet sediment trap was cleaned of

debris. Pictures of the completed work have been attached to this document.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action work on the culvert and basin was completed by 5/15/2020. The culvert was cleared of debris and raised to hopefully reduce the clogging issues seen at the lower gradeline. Rock guarding was installed at the new pipe elevation to prevent erosion around the pipe. Additionally, the inlet sediment trap was cleaned of debris. Pictures of the completed work have been attached to this document.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jon Armstrong

Signed: _____

Title: EH&S Rep, Sr.

Date: 5/22/2020 9:55:43 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402404717	FIR RESOLUTION SUBMITTED
402404736	Repaired Culvert 1
402404737	Repaired Culvert 2
402404745	Repaired Culvert 3
402404748	Repaired Culvert 4

Total Attach: 5 Files