

Document Number:
402415906

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 24500 Contact Name: Dan Richmond
 Name of Operator: PADCO LLC Phone: (918) 630-9912
 Address: 800 W 6TH STREET SUITE 1010 Fax: _____
 City: LOS ANGELES State: CA Zip: 90017 Email: dan@dsrinc.net

For "Intent" 24 hour notice required, Name: _____ Tel: _____
 Email: _____

COGCC contact: _____

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-121-09779-00
 Well Name: VENRICK Well Number: 4-A
 Location: QtrQtr: SWNW Section: 25 Township: 1N Range: 54W Meridian: 6
 County: WASHINGTON Federal, Indian or State Lease Number: _____
 Field Name: RAGO NORTH Field Number: 71850

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.027160 Longitude: -103.373720
 GPS Data: GPS Quality Value: 1.9 Type of GPS Quality Value: _____ Date of Measurement: 11/15/2007
 GPS Instrument Operator's Name: Tim Leibert
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: 1710
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	4949	4979			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24 #	133	90	133		VISU
1ST	7+7/8	5+1/2	14#	5,063	150	5,063	4,400	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4900 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 40 sks cmt from 1710 ft. to 1563 ft. Plug Type: STUB PLUG Plug Tagged:
 Set 75 sks cmt from 1563 ft. to 170 ft. Plug Type: OPEN HOLE Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 75 sacks half in. half out surface casing from 170 ft. to 60 ft. Plug Tagged:
 Set 17 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 1710 ft. of 5+1/2 inch casing Cut and Cap Date: 04/18/2020
 *Wireline Contractor: Brand X *Cementing Contractor: Yetter Well Service, Inc.
 Type of Cement and Additives Used: Type i & II
 Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

Casing was tite, Brand X could not get CIBP down so the CIBP was set using tubing instead of wireline with permission from field inspector (Susan Sherman in contact with Diana Burn); therefore there is no wireline vendor attachment on this report (see Yetter field tickets).
 Csg was stuck and could not get intended amount out; Diana Burn gave permission to amend recovery to what could be pulled (1710')

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Dan Richmond
 Title: Field Operations Super Date: _____ Email: dan@dsrinc.net

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type	Description

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
402415924	WELLBORE DIAGRAM
402415926	CEMENT JOB SUMMARY
402415928	OPERATIONS SUMMARY
402415930	OTHER

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)