

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2020

Submitted Date:

06/02/2020

Document Number:

689704806

FIELD INSPECTION FORMLoc ID 323960 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Byers, Jim		jbyers@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211359	WELL	PR	07/31/1997	GW	045-07119	FEDERAL GM 201-4	PR

General Comment:

Follow Up Field inspection

I, Inspector Mike Longworth, conducted a follow up field inspection.

Corrective action from 08/15/2019 inspection doc # 689703441:

Erosion trench on slope wall has not been repaired.

Install or repair required BMPs per Rule 1002.f.

C.A. Date 09/16/2019

Inspected Facilities									
Facility ID:	211359	Type:	WELL	API Number:	045-07119	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Corrective action from 08/15/2019 inspection doc # 689703441: Erosion trench on slope wall has not been repaired.						Date: 09/16/2019
Corrective Action: Install or repair required BMPs per Rule 1002.f.						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402411810	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5165150
689704807	Inspection 689704806 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5165149