

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402390039

Date Received:

05/05/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL & GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Blake Ford

970-776-6617

bford@extractionog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 679602518

Inspection Date: 04/23/2020

FIR Submit Date: 04/23/2020

FIR Status: _____

Inspected Operator Information:

Company Name: EXTRACTION OIL & GAS INC

Company Number: 10459

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 433397

Location Name: Winter Number: 29-D Pad County: _____

Qtrqtr: NENE Sec: 29 Twp: 7N Range: 67W Meridian: 6

Latitude: 40.552116 Longitude: -104.910562

FACILITY - API Number: 05-123-00 Facility ID: 433397

Facility Name: Winter Number: 29-D Pad

Qtrqtr: NENE Sec: 29 Twp: 7N Range: 67W Meridian: 6

Latitude: 40.552116 Longitude: -104.910562

CORRECTIVE ACTIONS:

1 ☒ CA# 138272

Corrective Action: Comply with Rule 603.f.

Date: 07/23/2020

Response: CA COMPLETED

Date of Completion: 05/01/2020

Operator
Comment:

Per rule 603.f-"Locations shall be free of equipment not necessary for use on that lease...."

The equipment present on location is necessary for the use on the lease and were pulled in preparation for our Lind Pad. When commodity prices went as low as they did, Extraction decided to shut-in most of their field. The rods, well heads, and automation are specifically laid out for their respected well. Collecting, moving, storing, and redistributing the equipment back to the site once production is turned back on could result in mixing up the equipment, resulting in unnecessary expenditures.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2  CA# 138273

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.

Date: 07/23/2020

Response: CA COMPLETED

Date of Completion: 05/01/2020

Operator
Comment: Soil cleaned up.

COGCC Decision: **Not Approved**

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Blake Ford

Signed: _____

Title: Environmental Supervisor

Date: 5/5/2020 1:12:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402390039	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files