

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402424448

Date Received:

06/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

sabre.beebe@bpx.com

Brown, Walt

970-385-1372

wabrown@fs.fed.us

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901828

Inspection Date: 05/20/2020

FIR Submit Date: 05/26/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326678

Location Name: GEARHART 1 - 32 GAS UNIT- N35N7W Number: 32SEnw County: LA PLATA

Qtrqtr: SEnw Sec: 32 Twp: 35N Range: 7W Meridian: N

Latitude: 37.260192 Longitude: -107.663692

FACILITY - API Number: 05-067- -00 Facility ID: 262345

Facility Name: GEARHART 01-32 Number: 2

Qtrqtr: SEnw Sec: 32 Twp: 35N Range: 7W Meridian: N

Latitude: 37.260192 Longitude: -107.663692

CORRECTIVE ACTIONS:

1 CA# 139289

Corrective Action: Control weeds.

Date: 06/15/2020

Response: CA COMPLETED

Date of Completion: 05/28/2020

Operator Comment: Herbicide treatment performed on noxious weeds on 5/28/20. Previous treatments performed on 7/15/2016, 7/17/2017, 7/10/2018, and 6/27/2019 See attached

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 139290

Corrective Action: Revegetation needs to be conducted for long term stabilization on soil stockpiles. Stormwater controls (ie: wattles) and eroison controls (ie mulch) are needed until stabilized with desirable perennial vegetation.

Date: 06/30/2020

Response: CA COMPLETED

Date of Completion: 06/10/2020

Operator Comment: The stock piles cited in the inspection do not appear to be soils associated with the creation of the well pad. In reviewing aerial photos of the area these piles appear after pad construction and during landowner construction of home and barns to the southwest of the well pad. However, given that BPX has no documentation to dispute the piles except Google Earth photos seeding, mulching and crimping of said piles has been conducted with native vegetation seeds. See attached work completion photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: corrective actions completed see attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Specialist

Date: 6/17/2020 10:08:12 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402424462	Weed control documentation
402424463	Seeding documentation

Total Attach: 2 Files