

Location			
Lease Road:			
Type	Access		
comment:	No Access roads.		
Corrective Action:	Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. Corrective Action Date 7/71/2020 See attached photos #.1, 2 & 3.		Date: <u>07/17/2020</u>
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Adequate		Date:
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds.		
Corrective Action:	Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 7/6/2020. See attached photos #.1, 2 & 3.		Date: <u>07/06/2020</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Building(s) in disrepair (around Pump jack motor).		
Corrective Action:	Inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Corrective Action Date 7/17/2020 See attached photos #.1, 2 & 3.		Date: <u>07/17/2020</u>
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 203561 Type: WELL API Number: 001-09121 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary. On Friday June 12, 2020 at approximately 11:30am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Invol Ferguson 14-33, Schreider and Company INC, at API # 001-09121 in Adams County Colorado. While there, I observed Shut in well. During this inspection the following possible compliance issues were observed:</p> <p>Access roads. Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. Corrective Action Date 7/17/2020. See attached photos #. 1, 2 & 3.</p> <p>Weeds. Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 7/6/2020. See attached photos #. 1, 2 & 3.</p> <p>Building(s) in disrepair (around Pump jack motor). Inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Corrective Action Date 7/17/2020. See attached photos #. 1, 2 & 3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	06/18/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900163	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5179023