

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2020

Submitted Date:

06/15/2020

Document Number:

697600944

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
GINTAUTAS, PETER 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	
MacLaren, Joe		joe.maclaren@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476892	SPILL OR RELEASE	AC	06/12/2020		-	County Road 22 Sales Line	EI

General Comment:

spill in roadside drainage ditch. Water present as seen in attached photo
 Landowner described as bubbles coming through soil in one area
 Landowner said he has observed water in ditch with source not known

Inspection of area indicates a drainage pipe coming from irrigated field to west of site of spill. Water in ditch may be from irrigation overflow/returns.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
	Gathering Line			
Comment:	pressure release from gas line Unknown fluid(s) in line at time of spill Landowner described that bubbles were coming up through soil at site of spill. spill shown in attached photos			
Corrective Action:	see COAs attached to approved initial form 19 Document 402419678 supplemental form 19 due within 10 days of discovery of spill. Other actions required within 45 days of discovery including investigation of spill			Date: 06/21/2020

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 476892 Type: SPILL OR API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402422703	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5175436
697600945	area where bubbles came up through soil (upper right of photo)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5175434
697600946	area where bubble emerged ground to left of white pipe	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5175435