

Well Name: McElvain Harmon 1A **API #** 05-067-08193
Well Name: McElvain 33-8-19 3 **API #** 05-067-08841 **NOTE:** This well belongs to Red Willow Production Company - 81295
Document Number: 693901844
Corrective Action: Approximately 1000 Canada thistles observed within the interim reclamation areas, and concentrated in the north. Revegetation is progressing in portions of the project area although sediment deposition and weed infestation is resulting in bare patches in the northern project area.
Control weeds. Revegetation of treatment areas is needed after infestation is controlled
Stormwater BMPs in the northern project area are not sufficient, and have failed. Erosional channeling is occurring downstream of BMPs and sediment is deposited where it settles downstream of the well pad fill slope.
Stormwater controls need to be installed to stabilize erosion within the project area.
Stormwater controls need to be selected, sized, installed, and maintained using good engineering practices such as those described by CDOT in their erosion control manuals
Correction Action Due: 7/2/2020
Action Completed: 6/26/2020
Action Taken: Applied chemical treatment to control Canada Thistle.
Improved stormwater controls in the northern portion of area.

