

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/30/2020

Submitted Date:

07/02/2020

Document Number:

690900110**FIELD INSPECTION FORM**Loc ID 446527 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10197Name of Operator: SANDRIDGE ENERGY INC (FEDERAL WELLS ONLY)Address: 1601 NW EXPRESSWAY STE 1600City: OKLAHOMA CITY State: OK Zip: 73118**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections
Boyer, David		dboyer@sandridgeenergy.com	
Murray, Richard		g.richard.murray@state.co.us	
Mair, Dylan		dmair@sandridgeenergy.com	
Neidel, Kris		kris.neidel@state.co.us	
Waldron, Emily		emily.waldron@state.co.us	

General Comment:

On June 30, 2020 COGCC Environmental Supervisor Alex Fischer conducted an environmental field inspection of the Pintail Tank Battery Spill/Release Point ID #477094. David Boyer and Wes from SandRidge were on site during this inspection.

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 155

Comment: [For more information regarding this release, please refer to Spill/Release Point ID #477094.](#)Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.Met with Operator on 6/30/2020.](#)

Date: 07/01/2020

Reportable: YES

GPS: Lat 40.573457

Long -106.381427

Proximity to Surface Water: 1518

Depth to Ground Water: 100

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:Comment: [Soil staining near loadout port and SWD wells.](#)Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a.](#)

Date: 08/31/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
<p>On June 30, 2020 COGCC Environmental Supervisor Alex Fischer conducted an environmental field inspection of the Pintail Tank Battery Spill/Release Point ID #477094. David Boyer and Wes from SandRidge were on site during this inspection. Weather was partially sunny and windy and temperatures about 50 degrees Fahrenheit.</p> <p>The following is a summary:</p> <p>Spill/Release occurred near the bottom of the 400 bbl produced water tank T-1603</p> <p>Salt staining was observed throughout the floor of the secondary containment and approximately 1-2 inches high on the liner.</p> <p>The tank was LOTO.</p> <p>Concrete supports/anchor/weights placed directly on secondary containment liner are deteriorating with exposed rebar.</p> <p>Metal sheeting pieces, bull plug, rebar, and other debris were located directly on the secondary containment liner.</p> <p>Folds in the liner were observed throughout the secondary containment.</p> <p>In places strong winds would blow beneath the liner.</p> <p>There was no evidence of fluids on the outside of the secondary containment.</p>	fischera	07/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402437346	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190111
690900111	INSP Photo Pintail Location 449274 Spill ID 477094 20200630	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190105