

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JUNE 29, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200135



PHOTO 1: THE FILL SLOPE WAS RECONTOURED TO MATCH THE SURROUNDING SLOPE. THE DISTURBANCE WAS SEEDED WITH AN APPROVED CPW SEED MIX AND EROSION CONTROL BLANKETS WERE INSTALLED OVER DISTURBED AREAS. THE EXISTING DIRT BERM WILL PROVIDE ADDITIONAL EROSION CONTROL.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JUNE 29, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200135



PHOTO 2: THE FILL SLOPE WAS RECONTOURED TO MATCH THE SURROUNDING SLOPE. THE DISTURBANCE WAS SEEDED WITH AN APPROVED CPW SEED MIX AND EROSION CONTROL BLANKETS WERE INSTALLED OVER DISTURBED AREAS. THE EXISTING DIRT BERM AT THE TOE OF THE SLOPE AND EXISTING VEGETATION WILL PROVIDE SEDIMENT CONTROL.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JUNE 29, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200135



PHOTO 3: EXISTING VEGETATION WAS PRESERVED OUTSIDE CONSTRUCTION BOUNDARY. NOXIOUS WEEDS WERE TREATED 07/03/20.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JUNE 29, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200135



PHOTO 4: THE WATERBAR WILL DIRECT RUN-OFF TO UNDISTURBED NATURAL VEGETATION REDUCING THE VOLUME OF RUN-OFF TO DISTURBED AREAS.