

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402453705

Date Received:
07/27/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>
		<u>SanJuanCOGCC@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901895
Inspection Date: 06/11/2020 FIR Submit Date: 06/12/2020 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325675

Location Name: FEDERAL LAND BANK 'D' UT-M34N9W Number: 36SESE County: LA PLATA
Qtrqr: SESE Sec: 36 Twp: 34N Range: 9W Meridian: M
Latitude: 37.143385 Longitude: -107.772720

FACILITY - API Number: 05-067-00 Facility ID: 215214

Facility Name: FEDERAL LAND BANK D Number: 1
Qtrqr: SESE Sec: 36 Twp: 34N Range: 9W Meridian: M
Latitude: 37.143385 Longitude: -107.772720

CORRECTIVE ACTIIONS:

1 CA# 139717

Corrective Action: Control weeds. Corrective action date is shortened to prevent spread of seed from mature thistle plants. Date: 06/30/2020

Response: CA COMPLETED Date of Completion: 07/07/2020

Operator Comment: Weeds treated and FIRR #402438388 filed for weed closure action item see attached.

COGCC Decision: _____

COGCC
Representative:

2 CA# 139718

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area.

Date: 07/15/2020

Response: CA COMPLETED

Date of Completion: 07/09/2020

Operator Comment: Erosional channel was from a breach in the irrigational ditch above the well pad. Landowner had repaired the ditch however the erosional channel along the pipeline onto the well pad was not addressed. Rock rundown installed to prevent further erosion over the pipeline. A berm installed to address other potential run onto the pad. see attached photos of work completed.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action completed to address erosion created by breach in irrigation ditch above the well pad.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 7/27/2020 3:05:08 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402453710	Erosion work completed
402453712	Weed treatment completion

Total Attach: 2 Files