

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/01/2020

Submitted Date:

07/29/2020

Document Number:

700300058

FIELD INSPECTION FORM

Loc ID 309370 Inspector Name: LABOWSKIE, STEVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10369
Name of Operator: NATURAL RESOURCE GROUP INC
Address: 801 WEST MINERAL AVE STE 202
City: LITTLETON State: CO Zip: 80120

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293813	WELL	SI	08/01/2017	GW	071-09451	MIRAH 1	SI

General Comment:

FLIR inspection to determine extent of venting and fugitive emissions. This inspection does not address corrective actions prescribed in recent inspections, conditions have not change, all corrective actions are still valid and required.

No Form 44 domestic tap registration

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	YES		
Comment:	uncontrolled venting through poly line that had been disconnected by landowner		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 293813 Type: WELL API Number: 071-09451 Status: SI Insp. Status: SI

Producing Well

Comment: Valves open and gas supplied to domestic poly line and to high pressure vessel which was venting through and open line with no PRV plumbed down toward ground

Corrective Action: Do not supply gas to domestic tap or tank, well must remain shut in, no viable operator.

Date:

