

FORM

6

Rev
02/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402443257

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 72400

Contact Name: Jeff Schneider

Name of Operator: PUBLIC SERVICE COMPANY OF COLORADO

Phone: (970) 867-9437

Address: 1123 W 3RD AVE

Fax: (970) 867-9137

City: DENVER State: CO Zip: 80223

Email: jeff@schneiderenergy.com

For "Intent" 24 hour notice required,

Name: _____ Tel: _____

COGCC contact:

Email: _____

Type of Well Abandonment Report:

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

API Number 05-077-07335-00

Well Name: ASBURY STORAGE UNIT-FED

Well Number: 5

Location: QtrQtr: SENW

Section: 14

Township: 9S

Range: 101W

Meridian: 6

County: MESA

Federal, Indian or State Lease Number: _____

Field Name: ASBURY CREEK

Field Number: 3200

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.276030

Longitude: -108.634030

GPS Data: GPS Quality Value: 0.1 Type of GPS Quality Value: PDOP

Date of Measurement: 05/19/2006

GPS Instrument Operator's Name: Paul Kellogg

Reason for Abandonment: ☐ Dry☒ Production Sub-economic☐ Mechanical Problems☐ Other _____Casing to be pulled: ☐ Yes☒ No

Estimated Depth: _____

Fish in Hole: ☒ Yes☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes☒ No

If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
DAKOTA	2734	2787	07/02/2020	CEMENT	2590

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	11+1/4	8+5/8	24	294	115	294	0	VISU
1ST	6+3/4	4+1/2	9.5	2,734	270	2,734	350	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 25 sks cmt from 2787 ft. to 2590 ft. Plug Type: CASING Plug Tagged: ☒

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set 35 sks cmt from 1500 ft. to 1310 ft. Plug Type: ANNULUS Plug Tagged: ☒

Perforate and squeeze at 1500 ft. with 35 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at 344 ft. with 50 sacks. Leave at least 100 ft. in casing 244 CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 25 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☒ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Cut and Cap Date: 07/08/2020
of _____

*Wireline Contractor: Rocky Mountain Wireline Service

*Cementing Contractor: Blac Frac Tanks Inc.

Type of Cement and Additives Used: Type 2

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

There is a permanent packer @ 2670'.
No flowline for the well, its a observation well in the gas storage field.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Jeff Schneider

Title: Consultant Date: _____ Email: jeff@schneiderenergy.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type **Description**

COA Type	Description

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
402443333	CEMENT BOND LOG
402443334	WIRELINE JOB SUMMARY
402443335	WIRELINE JOB SUMMARY
402443337	WIRELINE JOB SUMMARY
402455439	CEMENT JOB SUMMARY
402457174	CEMENT JOB SUMMARY
402457202	WELLBORE DIAGRAM

Total Attach: 7 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)