

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402461009

Date Received:

08/06/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77269

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Robert Redweik	(281) 891-1550	BRedweik@cogc.com
Rogers, Bob	(719) 340-1445	brogers@cogc.com
Kennedy, Herschel	(719) 767-3401	hkennedy@cogc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688307699
Inspection Date: 04/23/2020 FIR Submit Date: 04/28/2020 FIR Status:

Inspected Operator Information:

Company Name: CITATION OIL & GAS CORP Company Number: 17180
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77269

LOCATION - Location ID: 309606

Location Name: FALLOW 32-18-610S54W Number: 18SWNE County: LINCOLN
Qtrqr: SWNE Sec: 18 Twp: 10S Range: 54W Meridian: 6
Latitude: 39.180610 Longitude: -103.480215

FACILITY - API Number: 05-073-00 Facility ID: 218277

Facility Name: FALLOW 32-18 Number: 1
Qtrqr: SWNE Sec: 18 Twp: 10S Range: 54W Meridian: 6
Latitude: 39.180610 Longitude: -103.480215

CORRECTIVE ACTIIONS:

1 CA# 138420

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/29/2020

Response: CA COMPLETED Date of Completion: 07/13/2020

The wellhead stuffing box has been repaired and stained soil addressed.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 138421

Corrective Action: Maintain stormwater BMP at erosion rill in photo.

Date: 05/29/2020

Response: CA COMPLETED

Date of Completion: 07/13/2020

Operator
Comment:

Stormwater BMP has been maintained to address erosion rill.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions have been completed as documented by the attached photographs taken on or about July 14, 2020. The following items have been addressed: stained soil at wellhead, tank berm worn down, and offsite sediment transport in SW corner of tank battery. Additionally, the stuffing box leak has been repaired as discussed above.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Robert J Redweik

Signed:

Title: Director EHS/Regulatory

Date: 8/6/2020 9:19:08 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402461013	Corrective Action Photographs
-----------	-------------------------------

Total Attach: 1 Files