

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402429168

Date Received:

06/23/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100321

Name of Operator: ROCKY MTN NATURAL GAS LLC ADBA BLACK HILLS ENERGY

Address: 1515 ARAPAHOE ST TOWER 1

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Ally Little

Phone

307-778-2123

Email

ally.little@blackhillscorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402270

Inspection Date: 05/28/2020

FIR Submit Date: 06/08/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ROCKY MTN NATURAL GAS LLC ADBA BLACK HILLS ENERGY

Company Number: 100321

Address: 1515 ARAPAHOE ST TOWER 1

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 314169

Location Name: WOLF CREEK UNIT-68S90W Number: 35SENW County: \_\_\_\_\_

Qtrqr: SENW Sec: 35 Twp: 8S Range: 90W Meridian: 6

Latitude: 39.319435 Longitude: -107.411604

FACILITY - API Number: 05-097- -00 Facility ID: 314169

Facility Name: WOLF CREEK UNIT-68S90W Number: 35SENW

Qtrqr: SENW Sec: 35 Twp: 8S Range: 90W Meridian: 6

Latitude: 39.319435 Longitude: -107.411604

CORRECTIVE ACTIONS:

1 ☒ CA# 139563

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 07/08/2020

Response: CA COMPLETED

Date of Completion: 06/22/2020

Operator  
Comment:

Items on COGCC Inspection:  
Debris- All debris was removed from the pad.  
Degradation of pad surface- RMNG spread gravel stockpiles over pad and cleaned up tire ruts.  
Sediment migration- The roadside ditch that COGCC identified on the inspection was completed by USFS. They installed this ditch along the cut slope to allow drainage, but minimize runoff to site pad. RMNG did not alter this pad.

Sediment piles with no BMPs- Stockpiles of gravel were spread across site.  
Ruts and tracking- cleaned up by spreading gravel over site.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Operator needs to be aware that Location and Access road BMPs are required to be maintained/repared regardless of origination or ownership.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Thank you for bringing these maintenance items to our attention. All issues have been handled- we appreciated the pictures along with the inspection to help us figure out where the issues were.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ally Little

Signed: \_\_\_\_\_

Title: Environmental Professiona

Date: 6/23/2020 2:17:33 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

402429168	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files