

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/03/2020

Submitted Date:

08/04/2020

Document Number:

690200494**FIELD INSPECTION FORM**Loc ID 307317 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fitzgerald, Edie		ediefitzgerald@tcenergyllc.com	
Mack, Ronald		ronaldmack@tcenergyllc.com	
BAKER DAVID		dbaker@auroramp.com	
Dylan Thomsen		timothy.thomsen@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217446	WELL	PR	10/01/1996	GW	071-06223	APACHE CANYON 20-1	RI

**General Comment:**

This is a stormwater management inspection.  
See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			

Comment: There has been significant recent precipitation events that caused erosion along the main road. There are multiple culverts that have filled in with sediment which must be cleaned out and maintained. The next storm event could cause additional erosion and degradation of the road if BMP's aren't maintained. Maintaining BMP's will reduce erosion and additional issues. There was a backhoe operating along the road pushing mud and debris so maintenance appears to be under way. Ongoing maintenance needs to occur field wide.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 08/25/2020

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402459418	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5216464">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5216464</a>
690200495	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5216463">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5216463</a>