

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402379952

Date Received:
04/24/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901566
Inspection Date: 03/18/2020 FIR Submit Date: 03/23/2020 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325541

Location Name: HUBER CULHANE Number: 2-32 County: LA PLATA
Qtrqtr: SWNE Sec: 32 Twp: 35N Range: 8W Meridian: N
Latitude: 37.261730 Longitude: -107.765570

FACILITY - API Number: 05-067-00 Facility ID: 214976

Facility Name: HUBER-CULHANE Number: 1-32
Qtrqtr: SWNE Sec: 32 Twp: 35N Range: 8W Meridian: N
Latitude: 37.261730 Longitude: -107.765570

CORRECTIVE ACTIIONS:

1 CA# 137382

Corrective Action: Remove horse trailer from oil and gas location. Date: 04/24/2020

Response: CA COMPLETED Date of Completion: 04/24/2020

Operator Comment: Landowner does not want his property removed. The trailer is not burdening the operator at this time and is located on the fee surface owners land. This location has a surface use agreement between the operator and landowner, and therefore the edge of location is still the landowners. It is requested that the COGCC take time to meet with Hilcorp and landowner on location to discuss.

COGCC Decision: **Not Approved**

COGCC Representative: Operator response does not demonstrate that corrective action is addressed.

2 CA# 137383

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area. Stormwater controls need to be sized, selected, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals. Date: 04/24/2020

Response: CA COMPLETED Date of Completion: 04/24/2020

Operator Comment: They filled the erosion channel with top soil and reseeded. They also built a berm up on the edge of location to keep the storm water from running off

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mandi Walker Signed: _____

Title: Operation/Regulatory Tech Date: 4/24/2020 3:08:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402379952	FIR RESOLUTION SUBMITTED
402379973	Huber Culhane 2-32
402379974	Huber Culhane 2-32
402379975	Huber Culhane 2-32

Total Attach: 4 Files