

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402396606

Date Received:
05/13/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901209
Inspection Date: 12/13/2019 FIR Submit Date: 12/16/2019 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 333934

Location Name: J FRED HILL-N32N7W Number: 1NESE County: LA PLATA
Qtrqtr: NESE Sec: 1 Twp: 32N Range: 7W Meridian: N
Latitude: 37.043290 Longitude: -107.554030

FACILITY - API Number: 05-067-00 Facility ID: 258202

Facility Name: SQUIRES Number: 2
Qtrqtr: NESE Sec: 1 Twp: 32N Range: 7W Meridian: N
Latitude: 37.043290 Longitude: -107.554030

CORRECTIVE ACTIONS:

1 CA# 135386

Corrective Action: Revegetation needs to be installed by 4/1/2020. Weeds need to be controlled at the appropriate time but no later than 5/1/2020. Please note that herbicide application on young seedlings will likely adversely effect seedling establishment. Livestock exclusion may be needed for successful revegetation.

Date: 04/01/2020

Response: CA COMPLETED Date of Completion: 05/01/2020

Operator: Weeds removed
Comment: Re-contouring and control ditches installed Revegetation with mulch is completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 135387

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the western project area by 1/16/2020. Erosion controls such as mulching need to be installed at the time of seeding and no later than 4/1/2020.

Date: 01/16/2020

Response: CA COMPLETED

Date of Completion: 12/19/2019

Operator
Comment: re-staked to stop the wattles back in place to stop erosion from occurring

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mandi Walker

Signed: _____

Title: Operation/Regulatory Tech

Date: 5/13/2020 6:54:10 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402396606	FIR RESOLUTION SUBMITTED
402396607	SQUIRES 2_INC PHOTOS
402396608	SQUIRES 2_INC PHOTOS
402396609	SQUIRES 2_INC PHOTOS
402396610	SQUIRES 2_INC PHOTOS
402396611	SQUIRES 2_INC PHOTOS
402396612	SQUIRES 2_INC PHOTOS

Total Attach: 7 Files