

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402471281

Date Received:  
08/19/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531  
Name of Operator: GRIZZLY OPERATING LLC  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Axelson, Aaron</u>		<u>aaxelson@grizzlyenergylc.com</u>
<u>Pearl, Chase</u>	<u>720 402-7542</u>	<u>cpearl@grizzlyenergylc.com</u>
<u>Ghan, Scott</u>	<u>970 876-1959</u>	<u>sghan@grizzlyenergylc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402388  
Inspection Date: 07/24/2020 FIR Submit Date: 08/06/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC Company Number: 10531  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 416197

Location Name: Werner Number: 44C-23-692 County: \_\_\_\_\_  
Qtrqr: SWSE Sec: 23 Twp: 6S Range: 92W Meridian: 6  
Latitude: 39.507683 Longitude: -107.630219

FACILITY - API Number: 05-045- -00 Facility ID: 416197

Facility Name: Werner Number: 44C-23-692  
Qtrqr: SWSE Sec: 23 Twp: 6S Range: 92W Meridian: 6  
Latitude: 39.507683 Longitude: -107.630219

CORRECTIVE ACTIONS:

1 CA# 141089

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Clean up per Rule 906.a. Properly treat or dispose of oily waste in accordance with 907.e

Date: 08/24/2020

Response: CA COMPLETED

Date of Completion: 08/17/2020

The very small stain in wellhead cellar was associated with a grease fitting (bleed valve) on the casing valve. The

Operator Comment: routine greasing of valves is needed to ensure good mechanical condition and operation per Rule 605.d. High ambient temperatures can cause grease to bleed from the fittings. Both of the very small stains noted in the inspection have been removed.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Scott Ghan

Signed: \_\_\_\_\_

Title: Senior EHS Specialist

Date: 8/19/2020 2:46:04 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files