

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402467761

Date Received:
08/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|--------------------------|-----------------------|------------------------------------|
| <u>Labowskie, Steve</u> | | <u>steve.labowskie@state.co.us</u> |
| <u>Shorty, Priscilla</u> | | <u>pshorty@hilcorp.com</u> |
| <u>Ray, Mandy</u> | <u>(505) 599-4083</u> | <u>mray@hilcorp.com</u> |
| <u>Roy, Catherine</u> | | <u>catherine.roy@state.co.us</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 695103020

Inspection Date: 07/23/2020

FIR Submit Date: 07/29/2020

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 333608

Location Name: HUBER-TINKER-N34N8W Number: 9SWNW County: LA PLATA

Qtrqr: SWN Sec: 9 Twp: 34N Range: 8W Meridian: N
W

Latitude: 37.230040 Longitude: -107.756270

FACILITY - API Number: 05-067- -00 Facility ID: 215940

Facility Name: HUBER-TINKER Number: 1-9

Qtrqr: SWN Sec: 9 Twp: 34N Range: 8W Meridian: N
W

Latitude: 37.230040 Longitude: -107.756270

CORRECTIVE ACTIONS:

1 ☒ CA# 140810

Corrective Action: CONTROL WEEDS (CA DATE REMAINS THE SAME AS PREVIOUS INSPECTION
DOC#693901263 5-1-20

Date: 05/01/2020

Response: CA COMPLETED

Date of Completion: 08/14/2020

Operator Comment: The crew remove all the Musk Thistle and haul off, they also picked up the wire and posts and hauled them off too. All the culverts were cleaned as well. The photos are attached. The stained dirt was hauled off and disposed of properly. Cleaned and placed oil absorbent around the fuel pod and wellhead. Replaced the white flag marker that was at the wellhead that read, "NOTICE area being bioremediated with a microbial treated 100% agricultural by-product". The fuel pod / wellhead was cleaned and painted.

COGCC Decision: Approved via an AMI

COGCC Representative: based on photos submitted by operator ca's have been addressed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 8/17/2020 6:31:08 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---------------------------|
| 402467761 | FIR RESOLUTION SUBMITTED |
| 402467765 | Resolved photos |

Total Attach: 2 Files