

**Inspection Photos**  
**Operator: BP America**  
**API: 067-07153**  
**Date: 8/25/2020**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of erosion control blankets installed on the southern cut-slope. Blankets appear to be properly installed.



Photo 3. View of erosion control blanket installed in the southwestern project area. Small smooth brome plants observed near the toe of the slope.



Photo 4. View of the northern project area from the northwestern corner facing eastward. Vegetation is well established here with smooth brome and western wheatgrass.



Photo 5. View of reference area comprised of ponderosa pine woodland with understory of gambel oak, Sandberg bluegrass, and forbs such as purple aster.