

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402475746

Date Received:
08/26/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Mack, Ronald

ronaldmack@tcenergyllc.com

BAKER DAVID

dbaker@auroramp.com

Fitzgerald, Edie

ediefitzgerald@tcenergyllc.com

Dylan Thomsen

timothy.thomsen@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 690200496

Inspection Date: 08/03/2020

FIR Submit Date: 08/04/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 307884

Location Name: APACHE CANYON-634S68W Number: 24NWNE County: LAS ANIMAS

Qtrqtr: NWNE Sec: 24 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.074030 Longitude: -104.943110

FACILITY - API Number: 05-071- -00 Facility ID: 259100

Facility Name: APACHE CANYON Number: 24-02V

Qtrqtr: NWNE Sec: 24 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.074030 Longitude: -104.943110

CORRECTIVE ACTIONS:

1 CA# 140987

Corrective Action: Comply with Rule 1003.f.

Date: 08/14/2020

Response: CA COMPLETED

Date of Completion: 08/05/2020

Operator Comment: NOXIOUS WEEDS ALONG THE LEASE ROAD WERE TREATED ON 08/05/20.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 140988

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 08/28/2020

Response: CA COMPLETED

Date of Completion: 08/26/2020

Operator Comment: THE MAIN LEASE ROAD WAS SURFACE CROWNED TO ESTABLISH SHEET FLOW AND ELIMINATE THE TIRE RUTS AND SURFACE EROSION. THE BREACH IN THE DIRT BERM AND WATERBAR HAS BEEN REPAIRED. THE CUT SLOPE WAS DISTURBED WHEN THE SOIL STOCKPILE WAS REMOVED DURING RECENT REMEDIATION WORK ON THE FILL SLOPE. THE DISTURBANCE WAS SEEDED WITH AN APPROVED CPW SEED MIX AND EROSION CONTROL BLANKETS WERE INSTALLED OVER DISTURBED AREA FOR TEMPORARY SOIL STABILIZATION AND TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS ARE COMPLETE

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: EDIE FITZGERALD

Signed: _____

Title: SR. ENVIRONMENTAL TECH.

Date: 8/26/2020 2:48:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402475755	PHOTO LOG
-----------	-----------

Total Attach: 1 Files