

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: AUGUST 26, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200496



PHOTO 1: THE MAIN LEASE ROAD WAS SURFACE CROWNED TO ESTABLISH SHEET FLOW AND ELIMINATE THE TIRE RUTS AND SURFACE EROSION.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: AUGUST 26, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200496



PHOTO 2: THE CUT SLOPE HAD A SOIL STOCKPILE THAT WAS RECENTLY REMOVED DURING REMEDIATION WORK ON THE FILL SLOPE. THE DISTURBANCE WAS SEEDED WITH AN APPROVED CPW SEED MIX. EROSION CONTROL BLANKETS WERE INSTALLED OVER DISTURBED AREA TO PROVIDE TEMPORARY SOIL STABILIZATION AND TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: AUGUST 26, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200496



PHOTO 3: RUN OFF FROM THE LOCATION IS DIRECTED TO THIS BAR DITCH. THE BAR DITCH WAS RE-CONFIGURED INTO A WIDE PARABOLIC SHAPE TO REDUCE THE POTENTIAL FOR SCOURING.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: AUGUST 26, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200496



PHOTO 4: STORMWATER FROM THE BAR DITCH IS DIRECTED TO THE CULVERT INLET DOWN GRADIENT OF THE LOCATION.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: AUGUST 26, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200496



PHOTO 5: THE BREACH IN THE DIRT BERM AND THE WATER BAR AT THE TOE OF THE FILL SLOPE HAVE BEEN REPAIRED.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: AUGUST 05, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200496



PHOTO 6: NOXIOUS WEEDS ALONG THE LEASE ROAD WERE TREATED ON 08/05/20.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: AUGUST 05, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200496



PHOTO 7: NOXIOUS WEEDS ALONG THE LEASE ROAD WERE TREATED ON 08/05/20.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: AUGUST 05, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200496



PHOTO 8: NOXIOUS WEEDS ALONG THE LEASE ROAD WERE TREATED ON 08/05/20.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: AUGUST 26, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200496



PHOTO 9: CONDITION OF THE BULL THISTLE 08/26/20.