

HILL RANCH 31-14 API# 05-071-09567 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 01, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103252



PHOTO 1: THE REMAINING PIECES OF PIT LINER MATERIAL HAVE BEEN REMOVE FROM THE PRODUCTION PIT.

HILL RANCH 31-14 API# 05-071-09567 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 01, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103252



PHOTO 2: THE REMAINING PIECES OF PIT LINER MATERIAL HAVE BEEN REMOVE FROM THE PRODUCTION PIT.

HILL RANCH 31-14 API# 05-071-09567 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 01, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103252



PHOTO 3: THE REMAINING PIECES OF PIT LINER MATERIAL HAVE BEEN REMOVE FROM THE PRODUCTION PIT.

HILL RANCH 31-14 API# 05-071-09567 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 01, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103252



PHOTO 4: THE BULL THISTLE WAS MECHANICALLY REMOVED FROM THE LOCATION.