

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/04/2020

Submitted Date:

09/04/2020

Document Number:

693700581

FIELD INSPECTION FORMLoc ID 318201 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Max Knop		mknop@kpk.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240863	WELL	PR	07/01/2011	OW	123-08651	JAMES S HALEY TRUSTEE B 2	EI

General Comment:

COGCC response to flowline spill reported by Surface Owner

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 1

Comment: COGCC Staff received a phone call on 9/4/2020 at approximately 9:20 a.m. from the Surface Owner east of the James S Haley Trustee B #2 well regarding an oil spill along a pipeline. COGCC notified KPK and visited the location the same morning. There is an apparent flowline leak from the flowline associated to the James S Haley Trustee B #2 that surfaced and impacted surface area approximately 400 feet east of the well. Onsite Operator personnel stated that utility locates had been called and excavation would begin the afternoon of 9/4/2020. Spill is in an open area with unrestricted public access and therefore reportable under Rule 906.b.(1).A.

Corrective Action: Spill notification has been made to COGCC. Operator to notify local government pursuant to Rule 906.b.(6) and perform remediation pursuant to Rule 906.c. Operator shall consult with the Surface Owner as required by Rule 906.c.(2). Submit Form 19 Initial Report within 72 hours.

Date: 09/07/2020

Reportable: YES

GPS: Lat 40.075060

Long -104.976130

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402482823	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5239665
693700582	Spill area looking south	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5239661
693700583	Spill area looking west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5239662
693700584	Blowout point along flowline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5239663
693700585	Visual extent of Surface impacts looking NW	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5239664