

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2020

Submitted Date:

09/04/2020

Document Number:

694500225**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10551Name of Operator: ANDEAVOR FIELD SERVICES LLCAddress: 539 S MAIN STREETCity: FINDLAY State: OH Zip: 45840**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Schneider, Lindsay		Lindsay.Schneider@tsocorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463345	SPILL OR RELEASE	CL	03/25/2019		-	Duncan B-6 Lateral 276	EI

General Comment:

On 8/25/2020 COGCC Staff, Kris Neidel inspected the Duncan B-6 Lateral spill path. Spill 463345 and Remediation #12865. Weather was partly cloudy 70 degrees. COGCC staff, Kris Neidel walked the spill path from approximately 200 feet below to above the source. The flowline that was the source of the spill was removed from the spill area. No obvious signs of remaining impact were observed. Some pooled water was present in the creek, the creek was passable on foot. It was reported on 6/10/2019 that impact remains (doc number 402433886). This spill occurred on 3/14/2019, all impacted soils shall be remediated to table 910-1 standards. On an eForm 27 provide demonstration that the flowline abandonment was done per BLM rules. See attached Photos.

Environmental**Spills/Releases:**

Type of Spill: CONDENSATE

Estimated Spill Volume: 1

Comment: Spill 463345

Corrective Action: Remediate soil to Table 910-1 standards.

Date: 10/04/2020

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402483015	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5240279
694500226	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5240275