

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/15/2020

Submitted Date:

09/15/2020

Document Number:

696302479

FIELD INSPECTION FORM

Loc ID 423627 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96155
Name of Operator: WHITING OIL & GAS CORPORATION
Address: 1700 LINCOLN STREET SUITE 4700
City: DENVER State: CO Zip: 80290

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		WhitingEasternCO@Whiting.com	Eastern Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423673	WELL	TA	05/05/2020	OBW	123-33666	Pawnee Creek 9-57-18 1M	TA

General Comment:

Location			
Lease Road:			
Type	Access		
comment:	Cattle Guards have been removed, limiting driving acces to Wellhead, please back fill Access/Lease Road		
Corrective Action:	Repair and maintain lease road to comply with rule 204.		Date: 12/18/2020
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around Wellhead, See photos		
Corrective Action:	Comply with Rule 603.f.		Date: 09/30/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	TA Wellhead		
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 423673 Type: WELL API Number: 123-33666 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA. No MIT on Record. TA Status over 30 days (05.05.2020) per Rule 326.c.
"Well was found in state of Temporary Abandonment. Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b."
Form 6 #402376225 still "IN PROCESS" not yet approved.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 12/18/2020

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 09/14/2020 at approximately 11:36, I, Inspector Erica Petrie, conducted a Field Inspection at Whiting Oil and Gas Corp, Pawnee Creek 9-57-18-1M, Location #423627 in Weld County, Colorado. While there, I observed Production Operations During this Inspection the following possible compliance issues were observed: Access/Lease Road - Cattle Guards have been removed from the Lease Road. Making Driving to Wellhead non-accessible. Repair and maintain Lease Road to comply with rule 204. Corrective Action Date 12.18.2020 Weeds around Wellhead, see photos. Comply with Rule 603.f. Corrective Action Date 09.15.2020 TA. No MIT on Record. TA Status over 30 days (05.05.2020) per Rule 326.c. "Well was found in state of Temporary Abandonment. Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b." Form 6 #402376225 still "IN PROCESS" not yet approved. Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208. Corrective Action Date 12.18.2020 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p>	petrie	09/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696302483	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5248115