

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402490763

Date Received:

09/16/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Nica Hoshijo

Phone

303-358-9545

Email

nhoshijo@bisonog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696302427

Inspection Date: 09/10/2020

FIR Submit Date: 09/10/2020

FIR Status: _____

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 323023

Location Name: BASHOR-69N60W Number: 18SWNW County: WELD

Qtrqr: SWN Sec: 18 Twp: 9N Range: 60W Meridian: 6
W

Latitude: 40.750918 Longitude: -104.143250

FACILITY - API Number: 05-123- -00 Facility ID: 244657

Facility Name: BASHOR Number: 18-1

Qtrqr: SWN Sec: 18 Twp: 9N Range: 60W Meridian: 6
W

Latitude: 40.750918 Longitude: -104.143250

CORRECTIVE ACTIONS:

1 CA# 141800

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."

Date: 09/25/2020

Response: CA COMPLETED

Date of Completion: 09/14/2020

Operator Comment: Corrective actions were immediately taken to ensure equipment is maintained in good mechanical condition per Rule 605.d and that soil staining is addressed per Rule 907.e. Lease Operators were immediately notified of the corrective actions required, and service companies were contacted to schedule equipment and soil cleaning

activities. Lease Operators inspected equipment and performed the necessary equipment maintenance (e.g. tightening) to ensure the equipment is in good mechanical condition and contaminated soil was removed from the location. Please see attached photos that demonstrate compliance.

COGCC Decision: _____

COGCC
Representative:

2 CA# 141801

Corrective Action: Comply with Rule 603.f.

Date: 09/16/2020

Response: CA COMPLETED

Date of Completion: 09/14/2020

Operator Comment: Corrective actions were taken to address the unmarked risers just north of the tanks per Rule 603.f. Bull plugs were added to the risers and they were labelled to indicate they are for recirculation pumps if needed. Please see attached photos that demonstrate compliance.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Bison Oil & Gas II (Bison) is committed to operating responsibly and prioritizes environmental and safety concerns from COGCC. Bison took immediate action to resolve the Corrective Actions noted by the COGCC inspector and has provided documentaton to demonstrate compliance.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nica Hoshijo

Signed: _____

Title: EHS Manager

Date: 9/16/2020 2:32:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402490798	Bison - FIRR Photos
-----------	---------------------

Total Attach: 1 Files