

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402471495

Date Received:

08/19/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspection, Terra TEP

COGCCInspectionReports@terraep.com

Michael Gardner

970-623-4875

mgardner@terraep.com

Kellerby, Shaun

shaun.kellerby@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 701100247

Inspection Date: 08/18/2020

FIR Submit Date: 08/18/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335420

Location Name: CHEVRON-66S96W Number: 20NESW County: _____

Qtrqr: NESW Sec: 20 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.507528 Longitude: -108.134717

FACILITY - API Number: 05-045- -00 Facility ID: 335420

Facility Name: CHEVRON-66S96W Number: 20NESW

Qtrqr: NESW Sec: 20 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.507528 Longitude: -108.134717

CORRECTIVE ACTIONS:

1 ☒ CA# 141343

Corrective Action: Repair and maintain lease road to comply with rule 204.

Date: 11/19/2020

Response: CA COMPLETED

Date of Completion: 08/19/2020

Operator Comment: The inspection report states: " ... Vegetation (willows) on sides of the road crowding path way. Repair and maintain lease road to comply with Rule 204."

The willows growing along the side the road do no obstruct or hinder COGCC's ability to travel the road and gain access to our locations, or to conduct inspections. This road is traveled routinely by TEP personnel and the vegetation (i.e., willows) does not impede or restrict travel on this road. TEP is in compliance with Rule 204 below, which states:

"The Director and the authorized deputies shall also have the right at all reasonable times to go upon and inspect any oil or gas properties, disposal facilities, or transporters facilities and wells for the purpose of making any investigation or tests to ascertain whether the provisions of the Act or these rules or any special field rules are being complied with, and shall report any violation thereof to the Commission."

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: TEP is in compliance with Rule 204. The willows along the side of the road are not preventing COGCC inspectors from traveling this road, or entering upon and inspecting our properties and facilities. TEP personnel use this road routinely and the willows on the side of the road do not hinder or restrict access to this well location. No further actions are planned.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental

Date: 8/19/2020 4:40:56 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402471495	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files