

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/14/2020

Submitted Date:

09/15/2020

Document Number:

696201769

**FIELD INSPECTION FORM**

Loc ID 335887 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
3 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 10091  
 Name of Operator: BERRY PETROLEUM COMPANY LLC  
 Address: 5201 TRUXTUN AVENUE #100  
 City: BAKERSFIELD State: CA Zip: 90339

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		jcobb@bry.com	
		jarmstrong@bry.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298506	WELL	PR	01/13/2012	GW	045-17233	CHEVRON 6-25D	RI
335887	LOCATION	AC			-	Chevron F06 696	RI

**General Comment:**

On 9/14/2020 Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Berry Petroleum LLC??s Chevron F06 696 Location in Garfield County, Colorado.

This inspection is also a followup to #696201167 and #696201378, to determine compliance with the following corrective action: 603.f: Storage of unused equipment

It was observed in this inspection that corrective actions have not been addressed.

Refer to the "Good Housekeeping" section of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	<p>Previous inspection observed unused equipment (t-posts) stored on the southeast end of the Location, at the edge of the pad and inteirm areas, in an unworkman-like manner. Operator was required to comply with Rule 603.f.</p> <p>It was observed in this inspection that unused equipment remains stored on the Location: Corrective action has not been addressed and remains applicable.</p>		
Corrective Action:	Comply with Rule 603.f	Date:	05/08/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 298506 Type: WELL API Number: 045-17233 Status: PR Insp. Status: RI

Facility ID: 335887 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**COGCC Comments**

Comment	User	Date
This is the 3rd inspection documenting non-compliance with Rule 603.f; This Location is being considered for enforcement.	trujilloam	09/15/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402489451	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5247455">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5247455</a>
696201770	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5247445">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5247445</a>