

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402494846

Date Received:

09/22/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902200

Inspection Date: 08/27/2020

FIR Submit Date: 08/31/2020

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 306777

Location Name: TIFFANY-N32N7W Number: 1NWSW County: LA PLATA

Qtrqr: NWS Sec: 1 Twp: 32N Range: 7W Meridian: N
W

Latitude: 37.043930 Longitude: -107.565490

FACILITY - API Number: 05-067- -00 Facility ID: 264203

Facility Name: TIFFANY Number: 1R

Qtrqr: NWS Sec: 1 Twp: 32N Range: 7W Meridian: N
W

Latitude: 37.043930 Longitude: -107.565490

CORRECTIVE ACTIONS:

1 CA# 141560

Corrective Action: Remove and properly dispose of Russian thistle debris.

Date: 09/30/2020

Response: CA COMPLETED

Date of Completion: 09/22/2020

Operator
Comment: WEEDS REMOVED

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 141561

Corrective Action: Monitor revegetation areas throughout the remainder of the 2020 growing season. If significant desirable vegetation is not becoming established, then additional seeding work is required by 11/1/2020. Mulching material such as high quality hydromulch, hay mulch, etc. is needed for revegetation success and is considered a necessary erosion control practice on bare soils such as those within the project area.

Date: 11/01/2020

Response: CA COMPLETED

Date of Completion: 09/22/2020

Operator
Comment: RESEEDED

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 141562

Corrective Action: Stormwater controls (ie BMPs) and erosion controls (ie mulch, erosion control blankets, etc.) need to be installed to stabilize erosion within the project area. Corrective action is back-dated to original corrective action date as erosion is not sufficiently controlled within the project area.

Date: 11/15/2019

Response: CA COMPLETED

Date of Completion: 09/22/2020

Operator
Comment: EROSION CONTROLS RESTABILIZED

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: MANDI WALKER

Signed: _____

Title: OPERATION REGULATORY TECH

Date: 9/22/2020 9:54:43 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402494848	TIFFANY 1R_RESOLVED PHOTOS
-----------	----------------------------

Total Attach: 1 Files