

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2020

Submitted Date:

09/24/2020

Document Number:

699102468**FIELD INSPECTION FORM**Loc ID 432800 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432799	WELL	PR	11/01/2018	OW	123-37287	Latham O-K-2HNB	PR
432800	LOCATION	AC			-	Latham 34-2 Pad	AC
432804	WELL	PR	11/01/2018	OW	123-37290	Latham 44-41-2HNB	PR
435840	WELL	PR	11/01/2018	OW	123-38787	Latham O34-K31-2HC	PR
435841	WELL	PR	11/01/2018	OW	123-38788	Latham T-P-2HNB	PR
435842	WELL	PR	11/01/2018	OW	123-38789	Latham T34-P31-2HC	PR
435843	WELL	PR	11/01/2018	OW	123-38790	Latham 34-31-2HNB	PR
435844	WELL	PR	11/01/2018	OW	123-38791	Latham T44-P41-2HC	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	55 gallon drum needs to be in a secondary containment. See attached photos.		
Corrective Action:	Install berms or other secondary containment devices per Rule 906.d.(1).		Date: 10/26/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	432799	Type:	WELL	API Number:	123-37287	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	432800	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	AC								
Corrective Action:						Date:			
Facility ID:	432804	Type:	WELL	API Number:	123-37290	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435840	Type:	WELL	API Number:	123-38787	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435841	Type:	WELL	API Number:	123-38788	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435842	Type:	WELL	API Number:	123-38789	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435843	Type:	WELL	API Number:	123-38790	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435844	Type:	WELL	API Number:	123-38791	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 9/24/20 at approximately 1556hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Latham 34-2 Pad of Bonanza Creek Energy, at Location ID # 432800 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>55 gallon drum needs to be in a secondary containment. Install berms or other secondary containment devices per Rule 906.d.(1). With a corrective action date of 10/26/20.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	09/24/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102469	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5255394">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5255394</a>