

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/23/2020

Submitted Date:

09/27/2020

Document Number:

688308591**FIELD INSPECTION FORM**Loc ID 317124 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 94300Name of Operator: WARD & SON* ALFREDAddress: P O BOX 737City: OGALLALLA State: NE Zip: 69153**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	
Ward, Randy	(308) 280-0100	randy@wardoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236555	WELL	SI	05/01/2020	OW	121-09045	KLOEFKORN 1	SI

General Comment:

Stained soil on plastic by pit at tank battery. Properly dispose of waste.

Animal holes in oil tank berms.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	<input type="text"/>	<input type="text"/>
Other (Content)	<input type="text"/>	<input type="text"/>
Other (Capacity)	<input type="text"/>	<input type="text"/>
Other (Type)	<input type="text"/>	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient		
Comment:	Animal holes in berms.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 11/30/2020

Venting:

Yes/No	<input type="text"/>	<input type="text"/>
Comment:	<input type="text"/>	<input type="text"/>
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>	<input type="text"/>
Comment:	<input type="text"/>	<input type="text"/>
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected Facilities

Facility ID: 236555 Type: WELL API Number: 121-09045 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: 6/1/2020 last reported SI status to COGCC database.

Corrective Action: _____ Date: _____

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Inadequate		
Comment	Stained soil on plastic found near produced water pit at tank battery. No recent spill information in COGCC database.			
Corrective Action	Provide waste transportation and final disposition information in accordance with 907.b. (2) for all E&P waste transported off site.			Date: 10/12/2020

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688308622	Ward & Son Kloefkorn 1 TB sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5256358
688308623	Ward & Son Kloefkorn 1 stained soil pile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5256359
688308624	Ward & Son Kloefkorn 1 discharge from tank to pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5256360
688308625	Ward & Son Kloefkorn 1 animal holes in tank berms	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5256361