

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2020

Submitted Date:

09/29/2020

Document Number:

691201364**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Graber, Candice (Nikki) 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gintautas, Peter		peter.gintautas@state.co.us	
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476545	SPILL OR RELEASE	CL	07/17/2020		-	Facility #4 South	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.



**Environmental****Spill/Remediation:**

Comment: Inspection of Remediation #15691 progress. The initial clean up and removal of impacted soils has occurred as part of the repair. Extent of impact and remediation is unknown at this time. Per the initial Form 27 submitted on 7/7/2020 KPK had obtained permit approval from the Town of Frederick and excavation was scheduled to begin the week of July 13th, 2020. Inspection did not find evidence of any additional excavation or soil borings being performed at this site. Extent of impact is unknown at this time. The berm installed by Firestone Fire crews is still in place, no other BMP's are present

Corrective Action: Operator shall provide documentation of completed remedial actions within 45 days of the scheduled commencement date. Supporting documentation shall include confirmation soil samples to document removal of impacts from soil in the release area and a site diagram that illustrates the release extent and location of confirmation soil samples.

Date: 08/31/2020

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201365	Spill Location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5259047">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5259047</a>