

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2020

Submitted Date:

09/29/2020

Document Number:

691201364

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Graber, Candice (Nikki) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gintautas, Peter		peter.gintautas@state.co.us	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476545	SPILL OR RELEASE	CL	07/17/2020		-	Facility #4 South	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Inspected Facilities

Facility ID: 476545 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Inspection of Remediation #15691 progress. The initial clean up and removal of impacted soils has occurred as part of the repair. Extent of impact and remediation is unknown at this time. Per the initial Form 27 submitted on 7/7/2020 KPK had obtained permit approval from the Town of Frederick and excavation was scheduled to begin the week of July 13th, 2020. Inspection did not find evidence of any additional excavation or soil borings being performed at this site. Extent of impact is unknown at this time. The berm installed by Firestone Fire crews is still in place, no other BMP's are present

Corrective Action: Operator shall provide documentation of completed remedial actions within 45 days of the scheduled commencement date. Supporting documentation shall include confirmation soil samples to document removal of impacts from soil in the release area and a site diagram that illustrates the release extent and location of confirmation soil samples.

Date: 08/31/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402499941	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5259054
691201365	Spill Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5259047