

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/07/2020

Submitted Date:

10/07/2020

Document Number:

699102537

### FIELD INSPECTION FORM

Loc ID 447617 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments2 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447618	TANK BATTERY	AC	09/08/2016		-	GITTLEIN D04-24, Marie D4-72	AC

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained Soil around the compressor, needs to be removed. See attached photos.		
Corrective Action:	"Properly dispose of oily waste in accordance with 907.e."		Date: <u>10/30/2020</u>

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Emission Control Device	# 5		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Other	# 3		
Comment:	Sand Cans		
Corrective Action:		Date:	
VRT	# 1		

Comment:			
Corrective Action:			Date:
Type: VRU	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER			40.248000,-104.554900
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	60 BBLS
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
	Inadequate	Walls Insufficient		
Comment:	Pit needs Secondary Containment/ Berm. See attached photo.			
Corrective Action:	Install berms or other secondary containment devices per Rule 906.d.(1)			Date: 10/30/2020

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 447618 Type: TANK API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: AC

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Wednesday 10/7/20 at approximately 0800hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Gittlein D04-24, Marie D 4-72 Tank Battery of Noble Energy, at Facility ID # 447618 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Stained soil around the compressor, needs to be removed. "Properly dispose of oily waste in accordance with 907.e." With a corrective action date of 10/30/20.                      Pit needs secondary containment. Install berms or other secondary containment devices per Rule 906.d.(1). With a corrective action date of 10/30/20.                      See attached photos.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	burnsa	10/07/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102539	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264279">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264279</a>