

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:

Type					corrective date
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:	Calibration card is outdated.				
Corrective Action:				Date:	
Type: Pig Station	# 1				
Comment:					
Corrective Action:				Date:	
Type: Emission Control Device	# 2				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:	ECD scrubbers				
Corrective Action:				Date:	
Type: Bird Protectors	# 3				

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Secondary containment is inadequate to contain largest single tank plus sufficient freeboard.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 01/11/2021

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 433360 Type: TANK API Number: - Status: AC Insp. Status: SI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 10/9/2020 at approximately 13:50 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Murdoch 24-34 Tank Battery location #433360 in Larimer County, Colorado. While there, I observed insufficient containment berms around the crude oil tanks. During this inspection the following possible compliance issues were observed: Rule 605.a.(4). with a corrective action date of 1/11/2021. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	10/09/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402507867	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5266244
697002189	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5266211