

FORM

6

Rev
11/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402525706

Date Received:

11/04/2020

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 51130

Contact Name: Michael Nicol

Name of Operator: LOCIN OIL CORPORATION

Phone: (281) 362-8600

Address: 2445 TECHNOLOGY FOREST BD #710

Fax: (281) 419-6626

City: THE WOODLANDS State: TX Zip: 77381

Email: mnicol@locinoil.com

For "Intent" 24 hour notice required,

Name: _____

Tel: _____

COGCC contact:

Email: _____

Type of Well Abandonment Report:

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

API Number 05-103-08658-00

Well Name: FORK UNIT-FEDERAL

Well Number: 5-23-1-2

Location: QtrQtr: SWNW Section: 23 Township: 1S Range: 102W Meridian: 6

County: RIO BLANCO

Federal, Indian or State Lease Number: 44511

Field Name: DOUGLAS CREEK NORTH

Field Number: 17900

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.948660

Longitude: -108.815920

GPS Data: GPS Quality Value: 1.6 Type of GPS Quality Value: _____ Date of Measurement: 10/27/2010

Reason for Abandonment:

☐ Dry☐ Production Sub-economic☐ Mechanical Problems☐ Other _____

Casing to be pulled:

☐ Yes☐ No

Estimated Depth: _____

Fish in Hole:

☐ Yes☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:

☐ Yes☐ No

If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
MANCOS B	2358	2450	06/11/2010	B PLUG CEMENT TOP	2310

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	NA	24	0	180	180	180	0	
1ST	7+7/8	5+1/2	NA	15.5	0	2636	350	2636		

Subsurface hazards include, but are not limited to, the following: overpressured zones, underpressured zones, major geologic faults, salt sections, H₂S at concentrations greater than or equal to 100 ppm.

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 2310 with 5 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 58 sks cmt from 1220 ft. to 720 ft. Plug Type: CASING Plug Tagged: ☒
Set 35 sks cmt from 720 ft. to 410 ft. Plug Type: CASING Plug Tagged: ☒
Set 35 sks cmt from 410 ft. to 405 ft. Plug Type: CASING Plug Tagged: ☒
Set 62 sks cmt from 405 ft. to 3 ft. Plug Type: CASING Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 25 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☒ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: 06/16/2010 Cut and Cap Date: 06/16/2010 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 0

*Wireline Contractor: Perforators, Inc

*Cementing Contractor: Swabbco

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

Well was missing form 6s from records. Well was plugged in 2010. There will not be a form 42 flo for this well. Original Form 6S and cement reports are attached.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Aaron Katz

Title: NW Area Engineer Date: 11/4/2020 Email: aaron.katz@halliburton.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Katz, Aaron Date: 11/4/2020

CONDITIONS OF APPROVAL, IF ANY:

COA Type **Description**

COA Type	Description

Attachment Check List

Att Doc Num**Name**

402525706	FORM 6 SUBSEQUENT SUBMITTED
402525726	WELL ABANDONMENT REPORT (SUBSEQUENT)

Total Attach: 2 Files

General Comments

User Group**Comment****Comment Date**

Engineer	Form 6S was missing from well file. Reached out to Locin and recieved the original Form 6S and cement summaries from the operator. Form was entered by COGCC and all files from operator are attached. The well was plugged in 2010 and no From 42 FLO is available Surface location verified Production reporting PA status	11/04/2020
----------	---	------------

Total: 1 comment(s)