

# Inspection Photos

11/02/2020

Operator: TEP ROCKY MOUNTAIN LLC #  
96850

Location ID: 324382  
Garfield, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 324382



**Photo 1:** Photo taken from the Location, facing northwest.  
Reclamation in process.



**Photo 2:** Photo taken from the Location, facing northeast.  
Reclamation in process



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 324382



**Photo 5:** Photo taken from the western interim areas of the location, facing north. Photo shows noxious weeds remaining on the Location. Previous inspections observed seed dispersal in process. It was observed in this inspection that seed dispersal appears to have been allowed to be completed, as the majority of the weed's seed heads are now bare. Weeds have not been removed as indicated by the FIRR; Unable to find evidence that sufficient weed management activities to prevent establishment and spread of noxious weeds on and from the Location have been conducted.



**Photo 6:** See comments under photo 5.