

FORM
17Rev
11/20State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402524459

BRADENHEAD TEST REPORT

Step 1. Before opening any valves, record all tubing and casing pressures as found.

Step 2. Collect liquid and gas samples as required; consult Bradenhead Testing and Reporting Instructions and Guidance for field specific Orders at

<http://cogcc/reg.html#opguidance>

Step 3. Conduct Bradenhead test.

Step 4. Submit Form 17 within 10 days of test. Attach a wellbore diagram if not previously submitted or if wellbore configuration has changed since last wellbore diagram was submitted.

Step 5. Submit sample analytical results via Form 43.

1. OGCC Operator Number: 10633 3. BLM Lease No: _____

2. Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

4. API Number; 05-014-20655-00 5. Multiple completion? ☐ Yes ☐ No

6. Well Name: KATS Number: 8-2-34

7. Location (QtrQtr, Sec, Twp, Rng, Meridian): SWNE,34,1N,68W,6

8. County BROOMFIELD 9. Field Name: WATTENBERG

10. Minerals: ☒ Fee ☐ State ☐ Federal ☐ Indian

11. Date of Test: 11/02/2020

12. Well Status: ☐ Flowing☒ Shut In ☐ Gas Lift☐ Pumping ☐ Injection☐ Clock/Intermitter☐ Plunger Lift

13. Number of Casing Strings:

☒ Two ☐ Three ☐ Liner?

14. EXISTING PRESSURES

Record all pressures as found	Tubing: 0 Fm: _____	Tubing: _____ Fm: _____	Prod Csg 1277 Fm: _____	Intermediate Csg: _____	Surf. Csg 106
-------------------------------	------------------------	----------------------------	----------------------------	----------------------------	------------------

BRADENHEAD TEST

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (Bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals.

Describe character of flow in "Bradenhead Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper

Describe fluid type in "Bradenhead Fluid" column: H = Water H₂O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = NoneBuried valve? ☐ Yes ☒ NoConfirmed open? ☒ Yes ☐ No

BRADENHEAD SAMPLE TAKEN?

☒ Yes ☐ No ☒ Gas ☐ Liquid

Character of Bradenhead fluid:

☐ Clear ☐ Fresh☐ Sulfur ☐ Salty ☐ Black

Other:(describe)

Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:	Bradenhead Fluid:
00:00	<input type="checkbox"/> 0	<input type="checkbox"/>	<input type="checkbox"/> 1277		DOWN TO 0	NONE
05:00	<input type="checkbox"/> 0	<input type="checkbox"/>	<input type="checkbox"/> 1276		NO FLOW	NONE
10:00	<input type="checkbox"/> 0	<input type="checkbox"/>	<input type="checkbox"/> 1276		NO FLOW	NONE
15:00	<input type="checkbox"/> 0	<input type="checkbox"/>	<input type="checkbox"/> 1276		NO FLOW	NONE
20:00	<input type="checkbox"/> 0	<input type="checkbox"/>	<input type="checkbox"/> 1276		NO FLOW	NONE
25:00	<input type="checkbox"/> 0	<input type="checkbox"/>	<input type="checkbox"/> 1276		NO FLOW	NONE
30:00	<input type="checkbox"/> 0	<input type="checkbox"/>	<input type="checkbox"/> 1276		NO FLOW	NONE

Instantaneous Bradenhead PSIG at end of test: > 0

INTERMEDIATE CASING TEST

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (Bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals.

Describe character of flow in "Intermediate Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper

Describe fluid type in "Intermediate Fluid" column: H = Water H₂O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None

Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermediate Csg PSIG	Intermediate Flow:	Intermediate Fluid:
	00:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid	05:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
	10:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
	15:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
Character of Intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black Other:(describe) _____	20:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
	25:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
	30:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
	Instantaneous Intermediate Casing PSIG at end of test: > _____						

Comments: P&A. BH 106 PSIG. Gas samples.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: <u>Josh Rios</u>	Title: <u>Well Tech</u>	Phone: <u>(970) 4050469</u>
Signed: <u>Lindsey Organ</u>	Title: <u>Regulatory Coordinator</u>	Date: <u>11/10/2020</u>
Witnessed By: _____	Title: _____	Agency: _____