

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/10/2020

Submitted Date:

11/10/2020

Document Number:

690200809**FIELD INSPECTION FORM**Loc ID 311983 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		efitzgerald@ogrisop.com	
		vsantistevan@ogrisop.com	
		rmack@ogrisop.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265527	WELL	PR	12/23/2005	GW	071-07778	GOLDEN EAGLE 28-7	RI

**General Comment:**

This is a follow up of the previous stormwater management inspection.  
The corrective action of the previous inspection has partially been performed.  
See attached photos and additional details within this report.

Operator is directed to perform corrective actions outlined on this inspection report immediately.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			

Comment: The road had recently been regraded. There are culverts along the road that are still filled in with sediment. BMP's will need to be repaired and maintained. Additional BMP's are needed along the road side to prevent erosion. The corrective action of the previous inspection has partially been performed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	292694	2059207	
	292693	2059206	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690200811	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5288622">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5288622</a>