

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/11/2020

Submitted Date:

11/11/2020

Document Number:

693503774

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
319771 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10711
Name of Operator: PAINTED PEGASUS PETROLEUM LLC
Address: 16820 BARKER SPRINGS RD #521
City: HOUSTON State: TX Zip: 77084

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TROY	713) 818-8152	tmouret@p3petro.com	All Inspections
		jm@p3petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201314	WELL	SI	06/01/2019	GW	001-06717	MORAN 1	SI

General Comment:

Inspected Facilities

Facility ID: 201314 Type: WELL API Number: 001-06717 Status: SI Insp. Status: SI

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 10-30-2020
 Complaint Contacted:
 Date: 11-02-2020 In person on site
 FAC ID # 201314
 Location name: Moran 1
 Inspection Document # 699501851
 Complaint Document # 200449231
 Nature of Complaint: Leak
 Field Inspector Actions:
 On 11-2-2020, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to a leak on location. The complainant Jose Ruybal 8541 Imboden Rd Walkins stated the issues were occurring on a well site on his property. On 11-02-2020, me and Area field inspection Justin Medina drove to location and spoke with complaint who stated hearing leak off wellhead. We performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, we performed FLIRR video and videoed small leak around tubing on wellhead. Justin contacted operator P3 about leak by phone. Weather conditions: clear and dry Mechanical Issue corrective action was issued to P3. Reinsertion will be performed All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See inspection doc#699501851 for full inspection.	silverr	11/11/2020