

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402521365

Date Received:

10/29/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Michael Gardner

970-623-4875

mgardner@terraep.com

Kellerby, Shaun

shaun.kellerby@state.co.us

Inspection, Terra TEP

970-285-9377

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701100659

Inspection Date: 10/28/2020

FIR Submit Date: 10/28/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324186

Location Name: WILLIAMS-66S96W Number: 28SESW County: _____

Qtrqtr: SESW Sec: 28 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.488548 Longitude: -108.114757

FACILITY - API Number: 05-045- -00 Facility ID: 324186

Facility Name: WILLIAMS-66S96W Number: 28SESW

Qtrqtr: SESW Sec: 28 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.488548 Longitude: -108.114757

CORRECTIVE ACTIONS:

1 ☒ CA# 144022

Corrective Action: Repair and maintain lease road to comply with rule 204.

Date: 07/12/2020

Response: CA COMPLETED

Date of Completion: 10/29/2020

Operator Comment: Rule 204 simply states that COGCC is authorized to enter upon and inspect any oil and gas location/facility for the purposes of conducting inspections, investigations, etc.. The current condition of the access road does not inhibit or prevent COGCC from accessing or inspecting this location. Rule 204 does not mandate anything about

controlling vegetation along access roads. Further, rabbitbrush is a very desirable species and provides valuable forage and cover for big game and other wildlife. The vegetation along the access road is not in proximity to any ignition source, and therefore, it is not considered to be a fire hazard. The access road will continue to be maintained in a condition that provides adequate access to this location for the purposes of conducting day-to day operations, and providing sufficient access to COGCC for conducting site inspections.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This CA has been addressed in the Corrective Actions & Responses tab.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental

Date: 10/29/2020 10:14:30 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402521365	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files