

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402521486

Date Received:
10/29/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspection, Terra TEP</u>	<u>970-285-9377</u>	<u>COGCCInspectionReports@terraep.com</u>
<u>Kellerby, Shaun</u>		<u>shaun.kellerby@state.co.us</u>
<u>Michael Gardner</u>	<u>970-623-4875</u>	<u>mgardner@terraep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 701100664
Inspection Date: 10/28/2020 FIR Submit Date: 10/28/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324129

Location Name: AMERICAN SODA-66S96W Number: 34NWSE County: _____
Qtrqtr: NWSE Sec: 34 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.478358 Longitude: -108.093676

FACILITY - API Number: 05-045- -00 Facility ID: 324129

Facility Name: AMERICAN SODA-66S96W Number: 34NWSE
Qtrqtr: NWSE Sec: 34 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.478358 Longitude: -108.093676

CORRECTIVE ACTIONS:

1 ☒ CA# 144023

Corrective Action: Comply with Rule 603.f . Date: 10/03/2020

Response: CA COMPLETED Date of Completion: 10/29/2020

Operator Comment: In compliance with Rule 603.f, weeds are routinely controlled at this well location and the surface area around the production facilities. However, the vegetation noted within this inspection report is actually rabbitbrush that is observed growing along the access road. Rabbitbrush is a desirable species that provides critical forage to big game animals, and valuable cover to wildlife. There is no requirement within 603.f to remove / eradicate

desireable plant species from areas adjacent to access roads. The amount of rabbitbrush growing along the road does not interfere with, or inhibit access to this location. Nor is the rabbitbrush along the access road in close proximity to any ignition source, and therefore cannot be considered to be fire hazard. TEP will continue to maintain the surface of the well pad and the access road in a condition that is conducive to conducting day-to-day operations in a safe and compliant manner.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This corrective action has been addressed in the Corrective Actions & Responses tab. If desired, TEP personnel are available to further discuss this matter with COGCC staff.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental

Date: 10/29/2020 10:36:19 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402521486	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files