

Inspection Photos
Location Name: James S Haley Trustee B#2
Location ID: 318201



Photo 1 Disturbed area from spill remediation. No BMP's in place



Photo 2 1 Disturbed area from spill remediation. No BMP's in place

Inspection Photos
Location Name: James S Haley Trustee B#2
Location ID: 318201



Photo 3 What appears to be stained soil coming up from spill remediation.

Photo 4 inadequate berm around oily material from spill.

Inspection Photos
Location Name: James S Haley Trustee B#2
Location ID: 318201



Photo 5 1 Disturbed area from spill remediation. No BMP's in place



Photo 6 1 Disturbed area from spill remediation. No BMP's in place

Inspection Photos
Location Name: James S Haley Trustee B#2
Location ID: 318201



Photo 7 Well head.