

TEP ROCKY MOUNTAIN LLC
Strait SG 42-22
Location ID: 430567



No observed repair to cut slope behind tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP ROCKY MOUNTAIN LLC
Strait SG 42-22
Location ID: 430567



Crew installing a retaining wall.

TEP ROCKY MOUNTAIN LLC
Strait SG 42-22
Location ID: 430567



Unmarked deadman



Unmarked deadman

TEP ROCKY MOUNTAIN LLC
Strait SG 42-22
Location ID: 430567



Soft pad base is rutted.