

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402534846

Date Received:

11/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Distribution, Evergreen

cogcc.evergreen@enrllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690200610

Inspection Date: 08/31/2020

FIR Submit Date: 09/01/2020

FIR Status: _____

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC

Company Number: 10705

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 309060

Location Name: LORENCITO-634S66W Number: 29SENE County: LAS ANIMAS

Qtrqr: SENE Sec: 29 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.056100 Longitude: -104.794170

FACILITY - API Number: 05-071-

-00

Facility ID: 287543

Facility Name: LORENCITO Number: 8-29-34-66

Qtrqr: SENE Sec: 29 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.056100 Longitude: -104.794170

CORRECTIVE ACTIONS:

1 ☒ CA# 141603

Corrective Action: Comply with 1004 Rules and COA's.

Date: 11/30/2020

Response: CA COMPLETED

Date of Completion: 11/30/2020

Operator
Comment:

On 10/27/2016 a Form 4, Doc # 401194525, for Final Reclamation was submitted and on 01/26/2017 502b Variance, Doc # 401137816, was approved for this location. Inspection, Doc #673503873, was conducted on 11/16/2016. Work related to comments in Inspection, Doc #673503873 were completed on 01/12/2017. Recently, maintenance on access and minor erosion repairs were completed on 07/08/2020. Per regulation, Conditions of Approval for this location have been met. Along with vegetation, the location is "otherwise stabilized in such a way to minimize erosion" as documented by photos from the last four years. BMPs are maintained and there are no stormwater or erosion issues.
Complied with 1004 Rules and coa's

COGCC Decision: Approved pending re-inspection

COGCC Representative: Conditions of Approval have not been met. Please review document number 401137816.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please find the attached Photo's

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susan Wolfram

Signed: _____

Title: Sr. Safety Coordinator

Date: 11/17/2020 4:06:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402534846	FIR RESOLUTION SUBMITTED
402534848	Lorencito 8-29-34-66

Total Attach: 2 Files