

# Inspection Photos

11/06/2020

Operator: TEP ROCKY MOUNTAIN LLC #  
96850

Location ID: 334754  
Garfield, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 334754



**Photo 1:** Photo taken from the west end of the Location, facing south. Photos 1-3 provide an overview of the Location from south, west to north. Photos also show equipment observed in FIR 696201578 has been removed per the corrective actions.

**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850  
Location ID: 334754



**Photo 3:** See comments under photo 1.



**Photo 4:** Photo shows equipment not needed for production, or trash debris, is being stored on the Location.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 334754



**Photo 5:** Photo taken from the slopes on the southwest end of the Location. Photo shows erosion observed in inspection #696201578 has been repaired, however no BMPs have been installed to stabilize and protect slopes pursuant to Rule 1002.f.(2)C.



**Photo 6:** See comments under photo 5.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 334754



**Photo 7:** See comments under photo 5.



**Photo 8:** See comments under photo 5.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 334754



**Photo 9:** See comments under photo 5.

