

Inspection Photos

11/19/2020

Operator: GUNNISON ENERGY LLC - 10515

Location ID: 324457

Gunnison, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



Photo 1: Photo taken from the west end of the Location, facing east. Photo shows Location remains out of compliance with 1004 rules and corrective actions; Final reclamation of the Location/access road has not been conducted.



Photo 2: Photo taken from the northwest end of the Location. Photo shows anchor has not been removed.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



Photo 3: Photo taken from the southeastern areas of the Location, facing north. Photo shows areas where production equipment was Location. Gravel has not been removed from the areas, compaction alleviation conducted and reseeding.



Photo 4: See comments under photo 3.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



Photo 5: Photo taken from the east end of the Location, facing northwest. Photo shows Location remains out of compliance with 1004 rules and corrective actions; Final reclamation of the Location/access road has not been conducted. Photo also shows gravel remaining.



Photo 6: Photo taken from the access road, facing northeast. Photo shows Location remains out of compliance with 1004 rules and corrective actions; Final reclamation of the Location/access road has not been conducted.